

**REBITE DE FERRO
(CABEÇA REDONDA)****850.798 = 5/16 X 1/2****850.799 = 5/16 X 5/8****850.800 = 5/16 X 3/4****850.801 = 5/16 X 7/8****850.802 = 5/16 X 1"****850.803 = 3/8 X 3/4****850.804 = 3/8 X 7/8****850.805 = 3/8 X 1"****850.806 = 3/8 X 1.1/4****850.807 = 3/8 X 1.1/2****850.810 = 3/8 X 5/8****850.815 = 7/16 X 1"****850.816 = 7/16 X 1.1/4****850.817 = 7/16 X 1.1/2****850.820 = 1/2 X 1"****850.821 = 1/2 X 1.1/4****850.822 = 1/2 X 1.1/2**